



NO. 1570
2290
30-285



TO BE ON DETAIL (accepted)
OK

Correct to be
in oil drain
at Rear Motor
(accepted)
TO BE
ON DETAIL
OK



accepted +
on Detail
OK

5 1/2

13 1/4
13 1/4